



CUSTOMER FEEDBACK FORM

Vessel Name : M/V SEASPAN
 Date : ZAMBEZI
 Diving Location : 29/01/2022
 LAEM CHABANG PORT

Scope of Work:
 PROPELLER POLISHING &
 UNDERWATER PHOTO/VIDEO
 INSPECTION

1 = Poor.....5 = Excellent

1 2 3 4 5 n/a

Are you satisfied with the services provided by our dive team?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have you received proactive and on time updates from our office?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Did we deliver the services or/and supplied goods timely?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
How do you rate our technicians' knowledge related to job made?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Did our team apply appropriate Health, Safety & Environmental precautions during the services?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Has your equipment been returned to you in appropriate condition?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Are you satisfied with the overall quality of services?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Would you recommend "MaxiDive " to other persons / companies?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Other comments/suggestions for improvement

★ Customer Feedback Form must be delivered back to the MAXIDIVE CO., Ltd office and reviewed by management in seven working days from the date of job finished.

Officer in Charge name: R. Kovalenko
 Rank: C/O
 Signature:
 Date / Time: 29/01/2022
 16:00

Diving Supervisor JIRI GRIGERA
 Signature:
 Date / Time: 29/01/2022
 1600

Vessel Stamp: